Safety Data Sheet (SDS)

	Last updated 23 July 2019	
1. Product and Company Identificatio	<u>m</u>	
Product Name:	[Lys(Me3)9] - Histone H3 (1 - 21), H3K9(Me3) H - ART KQT ARK(Me3) STG GKA PRK QLA - OH AnaSpec, Inc. www.anaspec.com 34801 Campus Drive Fremont, CA 94555 Tel: 510-791-9560 Fax: 510-791-9572 Email: service@anaspec.com Kaneka Eurogentec SA, Rue du Bois Saint Jean 5 4102 Seraing Belgium Tel. +32-4-3727400 Fax. +32-4-3727500 E-mail info@eurogentec.com Kaneka Eurogentec Helpdesk	
Manufacturer/Supplier:		
Catalog Number	Tel. +32-4-3727665 AS-64452	
Relevant identified uses of the substance/preparation and uses advised against	For laboratory use only.	
Emergency information	Please contact the regional Eurogentec representation in yo country or Kaneka Eurogentec S.A. directly (from 8 am to pm)	

have not been thoroughly investigated.

GHS Hazard Classification:

GHS Physical Hazards:Not a dangerous substance according to the GHSGHS Health and Environmental Hazards:Not a dangerous substance according to the GHS

GHS Signal Words: None

GHS Hazard Statements: None

GHS Precautionary Statements: None

Potential Health Effects for:

Inhalation: If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Good hygiene practice requires that exposure be kept to a minimum and that suitable control measures be used in an occupational setting.

Ingestion: If swallowed, wash out mouth with water provided person is conscious. Call a physician.

Skin: In case of contact, immediately wash skin with soap and copious amount of water.

Eyes: In case of contact, immediately flush eyes with copious amounts of water for at least 15 minutes.

Chronic Exposures: No information available. We recommend limiting prolonged exposure.

Target Organs: No information available

HMIS Classification

Health hazard: 0 Chronic Health Hazard: 0 Flammability: 0 Physical hazards: 0

NFPA Rating

Health hazard: 0 Fire: 0 Reactivity Hazard: 0

3. Compositi	ion	
Ingredients/C	Components:	
Chemical N	Image: [Lys(Me3)9] - Histone H3 (1 - 21), H3K9(Me3) H - ART KQT ARK(Me3) STG GKA PRK QLA - OH	
	Molecular formula: NA Molecular weight: 2297.8 CAS-No NA EC-No NA	
4. First Aid	Measures	
Inhalation:	If dust is inhaled, remove from contaminated area. Encourage patient to blow nose to ensure clear passage of breathing. If irritation or discomfort persists seek medical attention.	
Ingestion:	If swallowed do NOT induce vomiting. If swallowed do NOT induce vomiting. If vomiting occurs, lean patient forward or place on left side (head-down position, if possible) to maintain open airway and prevent aspiration. Observe the patient carefully. Give water to rinse out mouth, then provide liquid slowly and as much as casualty can comfortably drink. Seek medical advice.	
Skin:	If skin or hair contact occurs: Flush skin and hair with running water (and soap if available). Seek medical attention in event of irritation.	
Eyes:	If this product comes in contact with the eyes: Wash out immediately with fresh running water. Ensure complete irrigation of the eye by keeping eyelids apart and away from eye and moving the eyelids by occasionally lifting the upper and lower lids. If pain persists or recurs seek medical attention.	

1

5. Fire Fighting Mea		Water aprov or for		
Extinguishing media:		Water spray or fog. Alcohol resistant foam.		
		Dry chemical powder.		
		BCF (where regulations permit).		
		Carbon dioxide		
Special firefighting procedures:		Alert Emergency Responders and tell them location and nature of		
		hazard.		
		Wear breathing apparatus plus protective gloves.		
		Prevent, by any means available, spillage from entering drains or water		
		course.		
		Use water delivered as a fine spray to control fire and cool adjacent		
		area.		
		DO NOT approach containers suspected to be hot.		
		Cool fire exposed containers with water spray from a protected location.		
		If safe to do so, remove containers from path of fire.		
		Equipment should be thoroughly decontaminated after use.		
Unusual fire and explosions hazards:		Emits toxic fumes under fire conditions		
6. Accidental Release	e Measures			
Spill response		l ignition sources.		
		Clean up all spills immediately.		
		Avoid contact with skin and eyes.		
		Control personal contact by using protective equipment.		
		Use dry clean up procedures and avoid generating dust.		
		suitable, labeled container for waste disposal		
Containment	Avoid all	personal contact, including inhalation.		
		ective clothing when risk of exposure occurs.		
		ell-ventilated area.		
		DO NOT enter confined spaces until atmosphere has been checked.		
		DO NOT allow material to contact humans, exposed food or food utensils.		
		Avoid contact with incompatible materials.		
Keep cont Avoid phy Always wa		dling, DO NOT eat, drink or smoke.		
		ainers securely sealed when not in use.		
		vsical damage to containers.		
		wash hands with soap and water after handling.		
		Use good occupational work practice.		
		Empty containers may contain residual dust which has the potential to accumulate		
		following settling. Such dusts may explode in the presence of an appropriate ignition		
	source.			
	Do NOT c	Do NOT cut, drill, grind or weld such containers		
PPE	Use persor	nal protective equipment		
	F F	<u> </u>		
7. Handling and Stor	rage			
Store at -20 °C, dry de	siccated and protec	ted from light. Store away from oxidizing agent.		

Γ

Store at -20 °C, dry desiccated and protected from light. Store away from oxidizing agent.

Engineering controls	Local exhaust ventilation is required where solids are handled as powders or crystals;
0 0	even when particulates are relatively large, a certain proportion will be powdered by mutual friction.
	Exhaust ventilation should be designed to prevent accumulation and re-circulation of particulates in the workplace.
	If in spite of local exhaust an adverse concentration of the substance in air could occur, respiratory protection should be considered. Such protection might consist of:
	(a): particle dust respirators, if necessary, combined with an absorption cartridge;(b): filter respirators with absorption cartridge or canister of the right type;
	(c): fresh-air hoods or masks Build-up of electrostatic charge on the dust particle, may be prevented by bonding and
	grounding. Powder handling equipment such as dust collectors, dryers and mills may require additional protection measures such as explosion venting.
	Air contaminants generated in the workplace possess varying "escape" velocities which, in turn, determine the "capture velocities" of fresh circulating air required to efficiently
	remove the contaminant.
PPE	Use personal protective equipment

9. Physical and Chemical Properties

Γ

Physical State	White Powder
Odour	Not available
Solubility in Water	Not available
Specific Gravity	Not available
рН	Not available
Boiling Point	Not available
Melting Point	Not available
Flash Point	N/A
Vapor Pressure:	N/A
Vapor Density:	N/A
vapor Density.	

10. Stability and Reactivity

Thermal Decomposition	No data available
Dangerous Products of Decomposition	No data available
Dangerous Reactions	COx, NOx when burned

Keep container tightly closed in a dry well-ventilated place. Store in -20 °C, dry refrigerator.

11. Toxicological Information

RTECS Number	N/A
Toxicity	No information available.
Health Hazards	Although ingestion is not thought to produce harmful
	effects, the material may still be damaging to the
	health of the individual following ingestion, especially
	where pre-existing organ (e.g. liver, kidney)
	damage is evident. In an occupational setting however,
	ingestion of insignificant quantities is not thought to be
	cause for concern.
Potential Hazards	Not available

AnaSpec Inc.

34801 Campus Drive, Fremont, CA 94555 Toll-Free: 800-452-5530 • Tel: 510-791-9560 • Fax: 510-791-9573

Carcinogenicity:		No significant acute toxicological data identified	
OSHA Permissible Exposure Limit(PEL) Data		N/A	
ACGIH Threshold Limit Values (TLV)		N/A	
Reproductive Toxicity:	,	No information available	
12. Ecological Information			
No information available.			
13. Disposal Considerations			
	by country, state and	tate and federal regulations. Legislation addressing waste d/ or territory. Each user must refer to laws operating in their	
14. Transport Information			
Hazard Class	N/A		
Identification Number	N/A		
Packing Group	N/A		
Proper Shipping Name (DOT)	N/A		
15. Regulatory Information			
US SARA Title III (Superfund Ame US Other: N/A	vironmental Respon endments and Reaut	se, Compensation, and Liability Act: N/A Phorization Act: N/A Prial Chemical Substances) Number: N/A	
EC Risk Statements: N/A			
Other Country Regulations: N/A			
16. Other Information			
experienced in handling potentiall to be correct but does not purper independent decisions regarding c	ly hazardous chemic ort to be all inclus completeness of the	cultural or cosmetic use. A technically qualified individual cals must supervise its use. The above information is believed tive and shall be used only as a guide. Users should make information based on all sources available. AnaSpec shall not g or from contact with the above product.	